



INCIDENT NAME
Big Bar Landslide

INCIDENT LOCATION
North of Big Bar on the Fraser River

DATE PREPARED
August 15, 2019





UPDATES

- Yesterday, an Expert Panel comprised of technical experts and First Nation leadership visited the Incident Command Post and the landslide worksites. This visit allowed the panel to share ideas, collaborate with the Incident Management Team (ICP) and provide expert insights into the challenges that ICP face.
- Rock scaling personnel have begun constructing a trail that will extend from the base of the landslide site back to the staging area. The route follows along the rivers edge before climbing slopes to the south. Scaling personnel will be able to access their worksite by foot and boat to avoid a descent down the rock face.
- Beach seining and fish wheel operations to support helicopter transport are continuing. Additional seining crews and helicopters are being added to the operation this week.
- Three new areas have been identified as alternate fish wheel sites to meet continually changing conditions.



The five metre (16 foot) waterfall that resulted from the landslide.

<u>Salmon Transported by Helicopter</u>				
Daily Total			Total to Date	
Sockeye: 770	Chinook: 420		Sockeye: 10,765	Chinook: 3,677

<u>Salmon Radio Tagging</u>				
Downstream From the Landslide			Transferred Upstream of the Landslide	
Sockeye: 125	Chinook: 97		Sockeye: 44	Chinook: 36